# **ARROW**

**REF** PL-00745

## Arrow® GlideThru® Peel-Away **Sheath over Dilator**

4.5 Fr.

Dilator accepts .018" dia. or smaller Spring-Wire Guide. Sheath accepts 4.5 Fr. or smaller catheter.

GlideThru™ Peel-Away Sheath: 4.5 Fr. x 2-3/4" (7 cm) Radiopaque over 4.5 Fr. Dilator

Rx only Warning: Read all package insert warnings, precautions, and instructions prior to use. Failure to do so may result in severe patient injury or death. www.teleflex.com/IFU California Prop. 65

MARNING: Cancer and Reproductive Harm.

www.P65Warnings.ca.gov

Not made with natural rubber latex.
Fluid path components are non-pyrogenic

**REF** PL-00745

### Arrow® GlideThru® Peel-Away **Sheath over Dilator**

4.5 Fr.

Dilator accepts .018" dia. or smaller Spring-Wire Guide. Sheath accepts 4.5 Fr. or smaller catheter.

### Contents:

1: GlideThru™ Peel-Away Sheath: 4.5 Fr. x 2-3/4" (7 cm) Radiopaque over 4.5 Fr. Dilator

Rx only Warning: Read all package insert warnings, precautions, and instructions prior to use. Failure to do so may result in severe patient injury or death. www.teleflex.com/IFU

California Prop. 65

A WARNING: Cancer and Reproductive Harm.

www.P65Warnings.ca.gov

Not made with natural rubber latex.
Fluid path components are non-pyrogenic.

**REF** PL-00745

# Arrow® GlideThru® Peel-Away **Sheath over Dilator**

4.5 Fr.

Dilator accepts .018" dia. or smaller Spring-Wire Guide. Sheath accepts 4.5 Fr. or smaller catheter.

### Contents:

1: GlideThru™ Peel-Away Sheath: 4.5 Fr. x 2-3/4" (7 cm) Radiopaque over 4.5 Fr. Dilator

Rx only Warning: Read all package insert warnings, precautions, and instructions prior to use. Failure to do so may result in severe patient injury or death. www.teleflex.com/IFU California Prop. 65

A WARNING: Cancer and Reproductive Harm.

www.P65Warnings.ca.gov

Not made with natural rubber latex.

Fluid path components are non-pyrogenic.







Arrow International LLC Subsidiary of Teleflex Incorporated 3015 Carrington Mill Blvd. Morrisville, NC 27560 USA



LBL061002 R00 (2022-07)

Arrow International LLC Subsidiary of Teleflex Incorporated 3015 Carrington Mill Blvd. Morrisville, NC 27560 USA



LBL061002 R00 (2022-07)

Arrow International LLC Subsidiary of Teleflex Incorporated 3015 Carrington Mill Blvd Morrisville, NC 27560 USA



LBL061002 R00 (2022-07)